

Drainage Works Currently Outstanding.

Job Number	Job Notes	Site Name	Area Name	Job Location
918980	Install new gully and lay 500mm wide strip of 10mm dbm 20mm high.	School Road	AMBERLEY	new gully opposite Mount View & ramp outside Mount View.
917965	carrigeway patch 4m x2mx 20mm, footway patch 2mx1mx20mm & raise 6 kerbs 10mm to stop water ponding	Deil Drive	ANGMERING	Outside property no 33
918689	rod gully to clear blockage	Station Road	ANGMERING	outside property called Prescott
918719	rod 5 gullies to find outlets and remove blockages or find any breaks	Station Road	ANGMERING	station road jct with woodlands ave as plan
918991	lower invert level in to manhole from gully approx 1.5 m of 150mm pipe work (Enquiry 261743)	The Pines	ANGMERING	o/s 1 the pines
824406	Lay 150mm x 66m plastic, edge of c'way, gully to gully, prove connection to ditch, re-profile ditch to act a storing capacity 2 x 1.2 x 45 spread spoil on site. Reinstatate as existing HRA C'way. Replace White Edge c'way where affected.	Staplefield Road	ANSTY AND STAPLEFIELD	From opposite J.W Cuckfield Road to 1 ACORN COTTAGE, see map (Constraints, bend, overhead cables, junctions)
917583	Build new bag headwall as per site specific sheet	Brantridge Lane	ANSTY AND STAPLEFIELD	s/o Heron Cottage 528085,128159
918930	Drainage Excavate in verge onto pipe line and install chamber downstream from pond.	Staplefield Lane	ANSTY AND STAPLEFIELD	At holding pond north of Whitehouse Farm 526894,126290
193574	EXCAVATE IN DITCH TO FIND PIPE. CLEAR DITCH TO ALLOW WATER TO GET AWAY. ROD PIPE FROM GULLY TO PROVE LINE.	Birham Road	APPLEDRAM	50M SOUTH OF NO 75. OPPOSITE POND.
916315	please rebuild low/tilted metal arterial drian cover (51cm * 44.5cm outside frame, see photograph attached to defect if required please ask WSCC person to print out)(STATS) which is low on eastern side (approx 35mm) to kerb, also repair section of missi	Surrey Street	ARUNDEL	C117/6 aprox 5m east of give way marking junction with Maltravers St - stats in sharepoint
917131	Reconstruct ditch where necessary / dig grips	Tortington Lane	ARUNDEL	TORTINGTON LANE, ARUNDEL. Near the junction with Chichester Road, for around 200m - leave debris in woodland
917168	Please Rod from manhole and investigate blockage	The Causeway	ARUNDEL	C117/1 southern end of wide entrance to car park & Arundel Lido - opp vehicle crossing to Police Station (see map and conway sheet on sharepoint)
918448	SEE NEW JOB NO 918869see Large worm required to investigate blocked culverts (suggest rod bone if possible)SEE NEW JOB NO 918869	Mill Road	ARUNDEL	stretch between the Childrens playground and the bridge over the mill stream by Swanborne Lake (between eastings:502054, northing:107404 and Eastings:502068 Northings:107185
918869	Large worm required to investigate blocked culverts (suggest rod bone if possible)	Mill Road	ARUNDEL	stretch between the Childrens playground and the bridge over the mill stream by Swanborne Lake (between eastings:502054, northing:107404 and Eastings:502068 Northings:107185
918924	Remove channel across footway and replace with Aco drainage 80mm or 100mm deep at 1.8 m long. Construct a false bottom so water flows onto the c'way	Maltravers Street	ARUNDEL	11 Maltravers St. Arundel, BN18 9AP .
916233	rod gullies to find pipe breakage	Malthouse Lane	ASHINGTON	outside the old malt house to end of road as plan
918696	rod gully to find any blockages see job number 823036 raised by m whitwell	Cricketers Close	ASHINGTON	outside number 3 towards telephone exchange, parked vehicles
824340	Install a total of 5no. Road gullies (double gully on adj to vehicle access) and connect with 150mm plastic pipe, connecting to existing system. As detailed on plan, Plus re-establish grips at approximate locations as marked on plan, 4 in total, Plus remo	Mill Lane	BALCOMBE	O/s property called Balcombe Mill. Constraints, bend, overhead cables, water, narrow lane.
917968	Install new 600x600 gullies and pipework location and levels to be agreed on site.As per site specific sheet	Mill Lane	BALCOMBE	o/s Balcombe Mill 531763,130464
918638	Drainage investigate and clear blockage, possible excavation in unmade drive.Park in driveway.	Handcross Road	BALCOMBE	Nr Redbridge Cottage 530287,130931
918872	Drainage Install tarmac bund across access approx 10mx0.5mx75mm	Mill Lane	BALCOMBE	o/s Balcombe Mill 531779,130450
64537	Walk, Talk and Build Carry out ditching works and improvements to existing drainage system, as detailed.	Bell Lane	BEPTON	Junction of Bell Lane / Church Lane, adjacent to 'The Old Rectory'.
64532	Please rod with worm to clear outlet which is solid with roots (Enquiry 252861)	Central Avenue	BERSTED	o/s No. 10
918654	rebuild existing gully & install 1 new gully .lay 17 m of 150mm pipe to connect to existing manhole	Shirney Lane	BERSTED	Shirney Lane/Rd A29 out side Barnfield House
194026	CLEAR DITCH AND HEADWALLS.APPROX 80M. SMALL BUSHES AND TREES IN AREA.	Bignor Road	BIGNOR	SOUTH OF BIGNOR PARK ROAD,NORTH OF BIGNOR MILL.BETWEEN E498244 N115118 AND E498251 N114925.
917244	rod from manhole to ditch and repair any breaks as nessary and dig and re-grade ditch for approx 3m (Enquiry 248877)	Bell Lane	BIRDHAM	junction with Bell Lane/Pinks Lane (see gdn in sharepoint) eastings:481870 Northings 99345
917355	please investigate and remove manhole and clear blockages as necessary	Crooked Lane	BIRDHAM	Crooked Lane near house called Dingles EASTINGS:481954 NORTHINGS:99558
918247	Clear pit, rod outlet to outfall, Clean out slot drain and replace frame and cover at pit with footway gully frame and cover, all in footway.	Cowfold Road	BOLNEY	o/s 1-4 Chapel Cottages 525817,122417 to 525785,122420
65535	Rod to determine blockage/break in pipe and repair if required	Bosham Lane	BOSHAM	outside of manor lodge as detailed on plan
65536	Rod to investigate possible break in line and repair as required	Main Road	BOSHAM	Outside prospect cottage as detailed on plan
917177	rod and repair as necessary (gully id D9366)	Walton Lane	BOSHAM	o/s 1-2 wayside cottages(see map and conway sheet in sharepoint) EASTINGS:481477 NORTHINGS:104570
918744	dig down in 2 locations find pipe and repair as necessary	Smugglers Lane	BOSHAM	out side house called Water Meadow as marked on map
918806	All work to be done are on SITE INSTRUCTION FORM AND MAP in Links and on SHARE POINT (Enquiry 234013)	Delling Lane	BOSHAM	Delling road E481001 N104594 to E481014 N104432
918741	dig down and repair pipe as necessary and rod (Enquiry 255583)	Corsetts Avenue	BROADBRIDGE HEATH	o/s 54
64883	Rod to investigate roots/ suspected break in pipe	Valebridge Road	BURGESS HILL	Just south of Jesters as detailed on plan /ON BEND EASTINGS:532386 NORTHINGS:121396 (ON SHAREPOINT)
822386	install soakaway	Birchwood Grove Road	BURGESS HILL	o/s Brichcroft
918006	Investigate gullies rod outlets to carrier.	Folders Close	BURGESS HILL	Nr LC2 532684,118120
918098	Investigate gully, chamber and pipe runs/outfalls.	Mill Road	BURGESS HILL	o/s 140 531464,119836
918264	Investigate gullies, rod outlets and locate outfalls	Burgess Hill Road	BURGESS HILL	Oak Tree Farm to West Riddens Farm 529563,122626 to 529419,122789
918506	Investigate footway gully adjacent to tree, may require excavation.As per Conway report 686	London Road	BURGESS HILL	O/s Bueno Appetito, 171, 530798,119275
918808	Drainage Clear gully sump of tarmac and concrete and rod outlet as per Conway report 18714	Greenlands Drive	BURGESS HILL	O/s 14 531665,117849
193488	PLEASE FIND OUTFALL AND LOCATE PIPE ROD BACK TO BREAK AND REPAIR PIPE. BREAK IS APPROX 16M FROM MANHOLE BEHIND POST BOX WHICH IS JUST NEXT TO DRIVE.	Bury Road	BURY	O/S THATCHED COTTAGE IN SOUTHERN END OF LAYBY OPPOSITE B2138. E500962 N115357
918870	PLEASE FIND OUTFALL AND LOCATE PIPE ROD BACK TO BREAK AND REPAIR PIPE. BREAK IS APPROX 16M FROM MANHOLE BEHIND POST BOX WHICH IS JUST NEXT TO DRIVE.	Bury Road	BURY	O/S THATCHED COTTAGE IN SOUTHERN END OF LAYBY OPPOSITE B2138. E500962 N115357
919482	Dig out grip, Dig out ditch to find headwall or pipe to other side of road and rod IF THERE IS A PIPE OR HEADWALL. (Enquiry 265347)	Back Lane	BURY	BACK LANE
189567	Request concrete gully surround removed and suspected void investigated and area reinstated. Area 1.2sqm. Enquiry 409102 refers. Follow up job to job 823002.	Willowbed Drive	CHICHESTER	Directly outside No14.
189940	Access cover rattles when driven over. Request new std heavy duty cover. John Bingham [BB] has knowledge of site. Site constraints = roundabout. Enquiry 409317.	Northgate	CHICHESTER	Approx 5m south of Broyle Road on "Northgate roundabout".
193573	PLEASE PUMP OUT MANHOLE FIND OUTLET. DIG DOWN AND FIND AND REPAIR PIPE.2 LANES APPROACHING JUNCTION & SMALL LANE CLOSURE REQUIRED	Broyle Road	CHICHESTER	SOUTHBOUND 40M BEFORE CHURCHSIDE. MANHOLE IN VERGE , OPPOSITE SPLITTER ISLAND. E486085 N105375
918073	please rod gully (water ponding over gully & along southern channel of West Pallant near corner with South Pallant, see attached photographs (Enquiry 410485)	West Pallant	CHICHESTER	D47/47 o/s eastern end of no 9 & near crossroads of all Pallants, (South, East & North Pallant)
918340	follow on job from job no 190215 please dig down possible broken pipe, repair as necessary and prove outfall	Albert Road	CHICHESTER	2 Albert Road, Chichester. (WORK IS IN CLAY LANE AT SIDE OF NO 2 ALBERT ROAD BETWEEN EASTINGS:484360 NORTHINGS:104848 AND EASTINGS:484264 NORTHINGS:104879
916587	follow on job from initial drainage investigation done by craig steer BB - please install new manhole cover and frame and please install 4m of 150m diameter pipe to side entry gully	Cocking Causeway	COCKING	TM REQUIRED 2 WAY LIGHTS o/s The Cottage between Eastings488312, Northing:119721 and Eastings:488327 and Northings:119737
918584	Clear out approx 10m of ditch and rod pipe from ditch to man hole in Deerswood garden (contactland owner before start Mr F Graham tel 01293 851259. Also repair broken pipe opp Hunters Oak	Faygate Lane	COLGATE	ditch Side of house called deerswood , pipe opp Hunters Oak E521749 N134712 AND E521766 N134584
918705	rod gully run as plan to find cause of flooding in properties	Blackhouse Road	COLGATE	between Heather Cottage and post box outside school,suggest working lime between 9.30am& 15.00pm
917137	Around 3-4 grips needed to solve water sitting on road - See photo link. (Enquiry 409851)	B2146 The Green to Hundred Acres	COMPTON	Approx 20m south of road named Hundred Acres.

825686	Carry out verge reduction to the southbound side of c'way, 60m x 2m, plus cut 4x 1m width grips to back edge of reduced verge to water to drain off. Remove spoil from site, plus install a double 600mm x 600mm c'way road gully opposite in access to coombes	Coombes Road	COOMBES	gullies on access to coombes farm and verge reduction opposite, 65m north of field access, s/bound. constraints, access, bens, overhead cables.
915875	carry out drainage survey as directed by Kevin Macknay / Brian Hammersley	Station Road	COWFOLD	as directed
824641	Further to GDN 247, with rods and sonde, track and trace pipe from gully to possible break, approx 35m in. Possibility is that the break is within garden of no. 8. Excavate and repair as necessary, reinstate as existing.	Poplar Close	CRAWLEY	o/s no. 8, NB: Contact property owner with prior notice, (Thursday's would be best works), Amit Parekh 07871 683425. (constraints junctions, overhead cables)
914381	Excavate ditch to expose pipr outlet from gully as per site specific sheet.	Maidenbower Lane	CRAWLEY	By west buttress wall of railway bridge. 528840,135675
917578	Install new f'way gully in edge of f'way and install soakaway in verge, as per site specific sheet.	The Birches	CRAWLEY	o/s 111 528583,137436
917591	Install new footway gully and patch cycleway.	Crawley Avenue	CRAWLEY	The Mardens Subway 525726,137170
919100	investigate surcharging c/w gully (Planned Drainage for WCO)	Church Street	CRAWLEY	opposite 10
917027	please clear ditch to expose outfall pipe and rod to clear	Selsay Road	DONNINGTON	o/s Taylors Cottage Between Eastings: 485474 northings:102102 and eastings:485489 northings:102057
917175	Re dig ditch as plan in sharepoint	Old Church Lane	DUNCTON	Old Church Lane
919729	please cut 2/3. grips with digger to minimize risk of ponding. Just north of northern end of lay-by. (Enquiry 410823)	A285 Thicket Lane To Earham Lane	EARTHAM	On inside of bend. between eastings:492721 northings:109552 and eastings:492813 and northings: 109633
918418	excavate either side of culvert, on both sides and dig out 5m of ditch and remove detritus	Wick Lane	EASEBOURNE	near Gosdens Farm. Between E:490026 N:123151 and E:490058 N:123137
823753	Side edge of Northbound c'way, clearing all vegetation, remove spoil from site, approx 235M x 0.5 to allow free flow into gullies. (Enquiry 306969)	Beeching Way	EAST GRINSTEAD	Approx 25m from Lewes road roundabout, northbound. (constraints, overhead cables, busy A road)
823897	From gully at junction with Lyton Road, s'bound, install new 150mm pipe. connect from gully to run along dbm f/w down into Lyton Park Ave and connect across 1m width verge to gully (opp no. 6) Reinstate as existing.	Holyte Road	EAST GRINSTEAD	J/W holyte Road and Lyton Road. (constraints, junctions, overhead cables)
916861	Drainage investigate 2no gully outlets and remove blockages or repair as required as per conway report no 192. Marked on c'way.	Charwoods Road	EAST GRINSTEAD	o/s hire centre 539087,139011
918003	Install replacement acco drain in footway, 2.5m o/s 189 and 1m o/s 199.	Garden Wood Road	EAST GRINSTEAD	o/s 189 and 199 538624,137750 to 538586,137760
64476	Walk, Talk and Build Drainage Works. Replace existing 300mm pipe with new 450mm pipe on same line. Reconstruct 'in line' gullies and fit with 600x600 gratings.	Norwood Lane	EAST LAVINGTON	Outside 'Sandrock' - information in sharepoint
828589	1. From ditch outlet, track/trace pipe with rods and sonde to break, approx 19.5m. Excavate onto defective 450mm concrete pipe in c'way and replace in 450mm plastic, to next sound section, approx 10m, reinstate as existing.	Sea Lane	EAST PRESTON	2x locations, JW with Gated Seaview Road, E&N 506918, 101561 and opp 23 E&N 506959, 102058 - Conraints, residential, overhead cables, bens.
918502	dig down and repair broken pipe as necessary	Roundstone Drive	EAST PRESTON	outside 71
65579	Investigate possible breaks in system and repair as required.	Barnham Road	EASTERGATE	os 100 and 94 as detailed on conways report. Paperwork on sharepoint
193517	PLEASE DIG OUT DITCH APPROX 30M, DISPOSE OFF SITE OF SPOIL	Church Lane	EASTERGATE	O/S CLARENDON HOUSE, BETWEEN E494375 N105243 AND E494423 N105215
918828	please use digger to dig out headwall, blocked pipe causing water to go onto carriageway (scoop job)Enquiry 261645)	Isling Bridge To Staples Hill	EBERNOE	approx 180m west of isling bridge
917073	Rod, CAT and GENNY to trace line (see conway defect 468)	Middleton Road	FELPHAM	Outside number 116 eastings:497058 northings:100295
918799	Dig down on 225 mm pipe after rodding to find blockage/ break between manhole and pond.rod from gully towards manhole.	Hoe Lane	FELPHAM	Hoe lane. Manhole is in the garage of house called Dukes Meadow . contact no 01243 587644 (john)
914838	rebuild edge of ditch - 6mL x 2mW of concrete bagwork, regrade ditch if necessary	Vann Road	FERNHURST	o/s Perry Edge / opp no55 just o/s 30mph limit
917154	Re dig grips as marked on plan. Fast road with sharp bends	A286 Sand Hollow Lane To Whites Lane	FERNHURST	o/s Kennels
189307	Construct new gully to intercept water flowing from newly installed footway/bus stop	High Street to Cross Lane	FINDON	O/S No. 2 and No. 78
918699	rod gullies to clear blockage	Steep Close	FINDON	first 2 gullies on leffhand side from high street (junction nearby)
918728	rod gully to manhole to clear any blockage or any break in pipe run	School Lane	FITTLEWORTH	outside no 21 (entrance to car park near by)
918728	rod gully to manhole to clear any blockage or any break in pipe run	School Lane	FITTLEWORTH	outside no 21 (entrance to car park near by)
918942	Lay concrete bag work to join up to existing head wall (3msq of concrete bags) to protect 150mm out let pipe. Bag work to be finished at ground level. Suppl and fix new concrete post and twin railin a squire to protect hole , (4 no posts and aprox 6m of t	Edburton Road	FULKING	EDBURTON ROAD
193089	Excavate new ditch to run from Mudberry Lane to just northwest of access track leading to Fortuna / Brooklands length = 250m. Provide new pipe under road to link new ditch with existing + create bagged headwall 2m x 2m. Non prejudice works request. Await	Newells Lane	FUNTINGTON	From Mudberry Lane to 4m north of access track leading to Brooklands / Fortuna.
917041	Please rod 2 x gullies and clear blockages	Newells Lane	FUNTINGTON	D class road. NEAR LEVEL CROSSING(MAP AND PHOTOS IN SHAREPOINT) between eastings:480172 northings:150645 and eastings:480193, northings:105616
64477	Bank stabilisation adajcent to existing water course. Approx 12m of sheet piling required.	Perrott Lane	GRAFFHAM	Between 'Meadow Brook Farm' and 'Quiet Court'.
193487	PLEASE DIG GRIPS INTO STREAM WILL NEED TO GO UNDER WIRE FENCE. MACHINE WORK SOME HAND WORK	Graffham Common Road	GRAFFHAM	JUNCTION WITH PERROTT LANE SEE PLAN, BETWEEN E492783 N118728 AND E492757 N118659.
193470	PLEASE CLEAR DITCHES APROX 230M MOST OF SPOIL CAN STAY ON SITE. RAISED FROM ENQUIRY 260600	Hollist Lane	HARTING	BETWEEN PENNS FARM AND HOLLIST FARM HOUSE E479950 N119852 AND E479799 N119715
916121	please reinstate/cut grips back to french drain and clean off concrete channel blocks thanks	B2146 Elsted Road To Torberry Lane	HARTING	see map in sharepoint eastings:478391 northings:119607 and EASTINGS:478126, NORTHINGS:119672.
918066	Drainage investigation required 3 x gullies, rod, investigate and repair as necessary (see maps in sharepoint)	B2146 Compton Down To Harting Hill	HARTING	2 x gullies by south lodge eastings:477552, northings:116184 and third gully north of bridgers pond, eastings:477432, northings 116743
918939	Please rod/investigate gully (gully id D3948) as there is a suspected blockage back towards entrance of Manor House.	North Lane	HARTING	o/s Manor House Eastings:478849 Northings:120120 see map on sharepoint
190208	rod gully to clear flood	Sergison Road	HAYWARDS HEATH	Outside No. 38
915445	fill potholes & edge erosion & rod gullies	Hurstwood Lane	HAYWARDS HEATH	junction with colwell lane
916743	Drainage works as marked as per site specific sheet.	Nursery Close	HAYWARDS HEATH	Throughout 532543,124158 to 532507,124119
918482	Investigate possible blockages as per Conway report 022858.Excavation may be required in c'way and/or verge.	Lewes Road	HAYWARDS HEATH	o/s and opposite no 72 534951,123270
918501	Investigate outlets from gullies as per Conway report 022947.C'way excavation may be required.	Ashenground Road	HAYWARDS HEATH	j/o Haywards Road 533148,123181 to 533127,123132
918796	Drainage raise setts etc., investigate adjacent chambers and gullies as marked as per site specific sheet.	Lewes Road	HAYWARDS HEATH	o/s 94 535161,123422
917077	ROD/ REPAIR PIPE WHERE BROKEN	Shoreham Road	HENFIELD	Blocked drain outside The Wicketts E521,472.84 N:113,353.19
917680	take out & relay 8m of granite setts to a 50mm upstand, rod culvert under drive of Dears Farm	West End Lane	HENFIELD	driveway of Dears Farm as marked on site 02/10/2012 (NM)
64509	Added to 2012 Ditch Maintenance Program. Target completion 31/09/12. Dig out ditch to below any piped levels. See spreadsheet for site details. Remove spoil from site.	Hoyle Lane	HEYSHOTT	See attached plan.
189079	Added to 2012 Ditch Maintenance Program. Target completion 31/09/12. Dig out ditch to below any piped levels. See spreadsheet for site details. Remove spoil from site.	Hoyle Lane	HEYSHOTT	See attached plan.
918598	Please dig down (possible pipe break)and rod /investigate cause of leak, and repair/reinstate as necessary(Enquiry 261797)	Hoyle Lane	HEYSHOTT	Opp 1 Bakerfield, os Bus Stop between E490159 N:117804 and E:490195 and N:117824
916788	please dig hole in trench to expose problem and contact client to advise(see notes from gang in sharepoint)	Redford Avenue	HORSHAM	os 117 (see gangs notes in sharepoint dated 21/8/2012)), eastings:516584 northings:131710
918090	CARRY OUT INVESTIGATION INTO SUBSIDENCE IN C'WAY . (Enquiry 256518) (Heave/ Subsidence)	Oakhill Road	HORSHAM	outside property no 45 OPPOSITE CLARENCE RD JUNCTION .
918619	rod gullies & repair any breaks found	Kerves Lane	HORSHAM	worst section Aimes Mill House & Aimesmill Bridge - EN 518205, 129401 to 518080, 129121
918681	rod gullies and report back any breaks in pipeline	Arthur Road	HORSHAM	opposite 10 A & outside number 31 parked cars a possibility
918683	rod gullies to find any breaks	Pondtail Road	HORSHAM	gully 1 junction with Old Millmeads gully 2 opposite Chesnut Gardens
825343	Rod from gully to break in pipe, dig down and repair as necessary, reinstate as existing, verge/dbm c'way. (Enquiry 255887)	Church Lane	HORSTED KEYNES	Out Side Fieldhurst, (constraints - school, junction, overhead cables - no through road, suggest carrying out OOH or non term time,)
919671	Clean out ALL gullies and jet out all pipe lines., sizes of pipe are required	The Street	HOUGHTON	B2139 HOUGHTON FROM Houghton Lane to Stable Antiques BOTH SIDES OF THE ROAD
916708	Drainage as marked as per site specific sheet. Excavate in footway.	College Lane	HURSTPIERPPOINT	J/o Hassocks Road 528979,115921
916742	Excavate in verge to clear blockage as per conway report 314.	Hassocks Road	HURSTPIERPPOINT	J/o Tott Hill 528764,116102

917853	drainage investigation required to repair suspected broken pipe	Trout Lane	ITCHINGFIELD	Immediately opposite & outside property no 9 as conway report form
918005	clear gully aprons & tops & re-dig grips	Plumtree Cross Lane	ITCHINGFIELD	from marlands to ark cottages
918831	please dig grips with digger and clear culvert/headwall as necessary (see map in sharepoint)	Glasshouse Lane	KIRDFORD	from house called wickers going north toward flooded area between E:500316 N:123063 and E:500515 N:123217
916341	rod gully	Blenheim Road	LANCING	vehicle access to Brooklands House
916671	blocked drain causing flooding rod & empty	Ring Road	LANCING	on ring road outside linden house.
916672	standing water in gully please rod	North Road	LANCING	o/s Boots Chemist adjacent to crossing point by tactics
189306	install new 9 inch pipe to connect to existing pipe from The Cottage garden. Construct new catchpit (C1/A FWS3) in verge to connect to new 9inch pipe. From catchpit lay new 6 inch pipe into gully. Park vehicle in driveway	Fordwater Road	LAVENT	O/S The Cottage between Fordwater Road and property garden.
65196	Walk, Talk and Build System Construct 2 No. dropped crossing above existing culvert. At eastern crossing fall footway towards existing brick parapet. Construct 'Letter Box' opening in parapet to allow water from carriageway to run back into stream.	Portsmouth Lane	LINDFIELD URBAN	Above existing culvert in Portsmouth Lane, adjacent to No. 2, By Sunte.
915925	Drainage install new gullies as per site specific sheet.	Eastern Road	LINDFIELD URBAN	o/s 2-2a 534912,125106 to 534934,125120
915926	Drainage install new gully and pipework in c/way	The Wilderness	LINDFIELD URBAN	Oaklea House 534977,125716
916741	Excavate in tarmac c/way onto dully outlet pipe approx 2m out from gully as per conway report no 330.	Portsmouth Wood	LINDFIELD URBAN	S/o 15 By Sunte 533887,125759
918270	Investigate gullies and rod outlets to outfall at pit	Appledore Gardens	LINDFIELD URBAN	29b to Pelham Road 534107,124803 to 534124,124782
918922	Drainage Addition to job no 918270 possible excavation in footway on to blockage see Conway report 023527	Appledore Gardens	LINDFIELD URBAN	o/s 29B 534109,124792
824069	Adjacent to LC11, from cover rod with sonde to locate collapse (approx 25ms west) dig down in f/w replace damaged sections as necessary, (225mm Plastic) Plus install inspection new insection chamber at point of break to allow future jetting.	Sea Road	LITTLEHAMPTON	From Lamp Column 11, adjacent to golf course see map
918487	Follow on job from job no 917409) Gully id D28436 please dig down and investigate and re-connect gully to pit 1 with invert higher than outlet in pit.(2mtrs 150mm UPVC pipe required)	Toddington Lane	LITTLEHAMPTON	opp (18 Mill lane) in Toddington lane (see map in sharepoint)
918511	Please lay approx 7m concrete edgings across access of Irvine House and neighbours house at the back edge of the footway, reprofile accesses approx 10msq so that water runs away from houses (PLEASE CONTACT DAVE BILLINGHURST TEL:07771961249 BEFORE START OF W	Fitzalan Road	LITTLEHAMPTON	Outside of Irvine House and next door neighbour
918653	lay 32m of 150mm pipe across road in 2 locations, connect to manholes	Sea Road	LITTLEHAMPTON	see map on sharepoint by miniature golf course
193671	EXCAVATE 20M OF DITCH DISPOSE ON SITE. DIG GRIPS EITHER SIDE OF BRIDGE.	Fitzlea Wood Road	LODSWORTH	WEST OF BRIDGE, O/S BARNETT'S COTTAGES. BETWEEN 494102 119205 AND 494106 119178.
916136	New Cover required 900x900x100 opening (BC66/1) (Enquiry 406424)	Surrey Road	LODSWORTH	Approx 40m north of junction with School Lane.
916908	New Cover required 900x900x100 opening (BC66/1) (Enquiry 406424), NO STATS REQUIRED	Surrey Road	LODSWORTH	Approx 40m north of junction with School Lane.EASTINGS: 492738, NORTHINGS:123729
193485	PLEASE CLEAR BOTH SIDES OF ROAD WHERE 400MM CULVERT GOES ACROSS.	Patworth Road	LURGASHALL	35 yr north of Herne House. E493687 N131815
193693	CLEAR 3 HEADWALLS AND APPROX 60M OF DITCH , SPOIL TO STAY ON SITE	Jobsons Lane	LURGASHALL	SOUTH OF LITTLE BROCKHURST, BEARDS COTTAGE AND SOUTH OF JAYS LANE BETWEEN E493973 N130597 AND E492699 127587
916630	adjust concrete bags to help capture water and dig ditch	Dial Green Lane	LURGASHALL	west of house called Greenfields map and drawings on sharepoint BETWEEN EASTINGS:493468 NORTHINGS:127166 AND EASTINGS:493586 NORTHINGS127165
916942	Gully id D29047 requires rodding/further investigation, conways jetted but could not clear with jetter (see conway sheet in sharepoint)	Church Lane	LYMINSTER	opposite tremeadow cottage, see map in sharepoint EASTINGS:502350 NORTHINGS:104790
915920	please install 1 new gully with slab behind (marked on site with X) and connect up to ditch with 6m 150mm pipe, also please cut 2 grips into ditch same side as new gully and 3 more grips on the other side of the road opposite ancton barn (all grips marked)	Ancton Lane	MIDDLETON-ON-SEA	o/s Ancton Barn between EASTINGS:497997, NORTHINGS: 100683 AND EASTINGS:498118 NORTHINGS:100642
918085	please investigate/rod and repair as necessary blocked gully	Elmer Road	MIDDLETON-ON-SEA	o/s 72
191419	Raise 2m x 2m of cobbles to height of surrounding cobbles [around 40-50mm]. Also relay 2m x 2m of footpath [dbm] also by around 40-50mm. Raise 5m of existing dropped granite sets by 15-20mm to prevent water running from c/w into footpath. This job is	North Street	MIDHURST	Access to Angel hotel. - Job to be done in January 2013
916991	Please rod gullyC26459 and clear any blockages	Rumbolds Hill	MIDHURST	o/s 7 eastings:488547 northings:121444
918797	sweep road as necessary	North Street	MIDHURST	as directed by John Bingham
917646	please dig/clear ditch by headwall	Milland Road	MILLAND	between eastings:484582 northings: 125657 and eastings484576 northings:125691 (Junction of Titty Hill Road and Milland Road just down from Iping churchyard
917049	(Enquiry 10731) refer to conway report 113, 2 x blocked gullies please investigate/rod clear blockages and repair as necessary	Langhurst Wood Road	NORTH HORSHAM	by entrance to broadlands business campus between eastings:517511 northings:135433 and eastings:517603 northings:135505
917855	rod and repair suspect broken pipes as conway job sheet	Leith View Road	NORTH HORSHAM	crawley road junction with leith view road as conway repair sheet
193315	EXCAVATE AND REPAIR 300MM PIPE. INVERT 800MM. 6M FROM MANHOLE EASTBOUND. ALSO CLEAR HEADWALL AND 40M OF DITCH EAST OF APPLELEA.	Honer Lane	NORTH MUNDHAM	PIPE REPAIR CORNER OF CORNWOOD AND APPLELEA. DITCHING WORKS EAST OF APPLELEA , BETWEEN E487823 N100276 AND E487917 N1002389
65103	Construct concrete apron around existing gully(id E44087)	Pipers Lane	NORTHCHAPEL	Adjacent Hortons Farm as detailed on plan
191135	Rod and trace to break in pipe. Dig down and repair/replace as required.	Nuthurst Road	NUTHURST	Outside of Forge Cottage see plan
825352	Further to GDN 39, SEE A1tched, rod from pit to break/obstruction and dig down and repair as necessary, reinstate as existing, (verge/DBM f/w)	Church Road	NUTHURST	passed the Church Road entrance into Mannings Heath, SEE Plan
916959	please rod to outfall and clear any blockages thanks (gully id A10252)	Nuthurst Street	NUTHURST	opposite Ferncroft.(map in sharepoint)
917400	1st two of the three drains are blocked, one is full of water, please rod to clear	Brighton Road	NUTHURST	Just after Coolthorpe Grange, after the doomsday crossroads.
190464	Gully appears cracked and knocked off access pit [area previously made safe under job 819633]. Request new heavy duty gully frame and cover installed in verge. Gully dimensions = 48" x 34". Site constraint = junction.	Woodhorn Lane	OVING	Approx 35m north of crossroads.
191037	Dig down and investigate potential chamber within footway. Track and trace with sonde and rods to location of chamber/direction of pipework.	Hook Lane	PAGHAM	Between No's. 5 and 4
193336	EXCAVATE IN DRIVEWAY FIND AND REPAIR 100MM PIPE	Springfield	PAGHAM	9 Springfield, APPROX 9.5M FROM BACK OF FOOTWAY. E489322 N98658
917019	Rod outlet to find blockage/break, dig down and fix as necessary	The Nyetimbers	PAGHAM	o/s no 7 and 5 between eastings:489508 northings:98629 and eastings:489499 northings:98614
917237	Please rod/repair as necessary (possible break in pipe approx 4m across road)	Lower Bognor Road	PAGHAM	TM WILL BE REQUIRED could be done under two way lights or possible lane closure? on bend by morells farm eastings490697, northing:100371
917238	Please rod and repair as necessary (possible broken pipe)	The Glade	PAGHAM	o/s no 8 eastings:489150 northings:97716
917241	Dig down and investigate potential chamber within footway. Track and trace with sonde and rods to location of chamber/direction of pipework.	Hook Lane	PAGHAM	Between No's. 5 and 4 stas in sharepoint under job no 191037
918886	please rod/investigate where two gullies connect up to/outfall to	The Glade	PAGHAM	by no 1 see map in sharpoint
918378	excavate pond down to chalk level and dispose of detritus off site	Long Furlong	PATCHING	opp Seth Evans workshops, behind layby E:509213 N:106103 (contractors can work in layby)
65534	Rod gully outlet to clear localised flooding	Station Road	PETWORTH	outside fire station as detailed on plan
918601	please install 1 x new gully and connect up to existing gully (approx 21m of 150mm pipe) please shape existing carriageway to channel water into gullys existing and new(see map in sharepoint)	Balls Cross Road	PETWORTH	site is marked with a white stick (photo in sharepoint) between eastings497626 northings:123389 and eastings:497615 N:123358 (see map in sharepoint near Gunters Bridge
918827	gully requires moving back to edge of carriageway and reprofile carriageway so that the water runs into the gully(Gully dimensions @ 560mm x 410mm.)(new gully grate required as old one is cracked) (Enquiry 410846)	Horsham Road	PETWORTH	Approx 80m west of lorry route. Eastings:499945 northings:122665
826434	1. From junction with Holmbush Lane to o/s Rosewood house, carry out 0.5m x 315m verge reduction on both n/bound and s/bound, Plus 60m x 0.5m o/s Little Holmbush, Holmbush Lane, remove spoil from site, See Map for locations. 2. Dig out 1m3 sumps at inlet	Clappers Lane	POYNINGS	Three locations, O/s Little Holmbush, Holmbush Lane. O/s Rosewood Hse to J.W Little Holmbush Lane. (constraints, narrow lane, bends, Overhead cables) (STATS E&N 525070, 112640 to 525070, 112705 & 524859, 113614 to 524863, 113954)
918413	raise 1 gully install 1 new pit install 2 doll posts and un cover buried gullies follow on from job number 916788 as discussed with Rod Bone	Clappers Lane	POYNINGS	near kennels and throughout road
916667	rod gully to find block	Rectory Close	PULBOROUGH	Outside number 29 for approx 50 yards
917356	raise 4 gullies by approx 30mm & patch carriageway approx 10m2 as marked on site	Stane Street	PULBOROUGH	as marked on site and attached plan
191342	Rod and trace to suspected break in pipe. Repair or replaces as required.	Nyewood Road	ROGATE	Between Sandhill Pond House and Owls Corner.
916126	Please build concrete bag headwall in durleighmarsh	Durleighmarsh	ROGATE	eastings:478477 northings: 123519 (currently barriered off)

916128	please cut grips	A272 Durlieghmarsh Lane To Slade Lane	ROGATE	between eastings:477306, northings:124026 and eastings: 479410, northings:123628
916825	Please investigate cause of water coming up through carriageway, and report findings back to client. Thank you	North Street	ROGATE	In the middle of North Street by the Whitehouse
918647	Drainage Ditch clearing approx 450m with JCB.	Bonnetts Lane	RUSPER	Charlwood Road To Olde Cottages 525401,139671 to 525323,139378
193576	CLEAR VEGETATION. EXCAVATE APPROX 4M OF DITCH TO GULLY TO DRAIN AWAY. ON BEND	Selsey Road	SELSEY	SOUTH CORNER OF NORTON CORNER COTTAGES E486117 N94845
824584	Further to GDN 332, dig down on broken pipe in f/w and replace as necessary, reported to be 0.5m in from gully (modular paved f/w).	High Street	SELSEY	B2145/3 o/s Selsey Press Ltd & just south of Fire Station car park - opp Lloyds Pharmacy (on southern corner of Malthouse Rd) (constraints, high street, ped lights, fire station, junctions)
916062	Renew 38m of 225mm pipe construct 2/3 new manholes, clear various ditches /headwalls to remove any constrictions. New pipework to be laid in footway. (Enquiry 253219)	Chichester Road	SELSEY	opp Comptons Farm Shop and o/s Comptons . Stats already in sharepoint in same folder as plan
917151	Please rod gully to prove outlet (GULLY ID C11948)	New Road	SHOREHAM-BY-SEA	gully in front of frosts car park
193311	DIG APPROX 40M OF DITCH AND DISPOSE FROM SITE.	Highleigh Road	SIDLESHAM	OPPOSITE PROPERTY LONGACRE E484544 N98021 AND E484549 N97970
193672	EXCAVATE DITCH APPROX 40M AND FIND HEADWALL. DISPOSE OF SPOIL OFF SITE.	Street End Road	SIDLESHAM	APPROX 50M SOUTH OF STREET END LANE. BETWEEN E485287 99205 AND 485342 99182. SOUTH OF ANCHOR PUB.
189211	Empty Soakaway and jet lines connecting to soakaway.	Horsham Road	SLAUGHAM	On island at J/w Old Bright Road South. See plan for details.
193462	Dig down and replace broken/disjointed section of pipe.	Slaugham Lane	SLAUGHAM	O/s entrance to Highlands and Highbanks
917180	Please Rod and Repair as necessary	Cuckfield Lane	SLAUGHAM	entrance to Hollingbury Lodge Between EASTINGS: 525425 NORTHINGS:126126 AND EASTINGS:525436 AND NORTHINGS:126125
917986	Investigate gullies rod outlets to main and check outfall	Warninglid Lane	SLAUGHAM	Slatehouse Farm to Firtree Cottage 524271,126519
918589	Drainage investigate, locate and repair blockages as per Conway Report 022932	High Street	SLAUGHAM	j/o London Road and High Beeches Road 526373,130209
64838	Clear trash screen and ditch at trash screen with JCB/ON BEND	Lyons Road	SLINFOLD	Opp Limes house Adj Two Oaks Additional Operative required to assist with manual clearance!
918097	Trash Screen to culvert blocked (see map & Photo)	Lyons Road	SLINFOLD	as marked on plan
825889	From chamber, replace 6.5m x 150mm pipe in plastic, 0.75m to invert, within hra f/w, reinstate as existing, n/bound (Enquiry 249502)	Stein Road	SOUTHBOURNE	Outside No 71 in f/w (constraints, level crossing, school)
825895	From road gully, excavate and lay 3m x 150mm pipe in plastic to connect from gully to 225mm clay carrier in verge. 0.75m to invert. across verge/x-over to avoid tree, see plan. (hra x-over), reinstate as existing, s/bound (Enquiry 249502)	Stein Road	SOUTHBOURNE	o/s and between 76 & 78 (constraints, level crossing, school)
65569	please rod to find blockages and dig to repair as required.	Station Road	SOUTHWATER	outside 5 as detailed on jetting plan.
917176	Please ditch out ditch to expose outfall pipe (Enquiry 258037)	Two Mile Ash	SOUTHWATER	adjacent to Christs Hospital School main gates on 2 Mile Ash Road heading south (see map in sharepoint) Between EASTINGS: 515549 NORTHINGS:128650 AND EASTINGS:515556 AND NORTHINGS 128662
189222	Added to 2012 Ditch maintenance program. Target completion 30/09/2012. Dig out ditch to below any piped levels. Remove spoil from site. See spreadsheet for site details.	School Lane	STEDHAM-WITH-IPING	Ditch down school lane
194076	FILL VOID WITH LEAN MIX CONCRETE 18MX400MMX400MM (WIDEST). CLEAN DITCH AND DIG GRIPS.	Iping Lane	STEDHAM-WITH-IPING	Next to the old cemetery EITHER SIDE OF LAYBY.SEE PLAN
917189	clear ditch, dig grips and rod pipes as plans	Fitzhall Road	STEDHAM-WITH-IPING	o/s Bridgelands Farm plans in sharepoint
917647	please dig/clear ditch by headwall	Iping Lane	STEDHAM-WITH-IPING	between eastings:484582 northings: 125657 and eastings484576 northings:125691 (Junction of Titty Hill Road and Milland Road just down from Iping churchyard
918915	repair pipe and investigate void in centre of road	Monastery Lane	STORRINGTON	opposite number 1 spring cottages(this will need a road closure)
189076	Added to 2012 Ditch Maintenance Program. Target completion 31/09/12. Dig out ditch to below any piped levels. See spreadsheet for site details. Remove spoil from site.	Glattling Lane	SUTTON	See attached plan.
189221	Added to 2012 Ditch maintenance program. Target completion 30/09/2012. Dig out ditch to below any piped levels. Remove spoil from site. See spreadsheet for site details.	Bignor Road	SUTTON	Stretch of Bignor Road, heading south from Sutton to Bignor
190975	Added to 2012 Ditch maintenance program. Target completion 30/09/2012. Dig out ditch to below any piped levels. Remove spoil from site. See spreadsheet for site details.	Bignor Road	SUTTON	Stretch of Bignor Road, heading south from Sutton to Bignor
193312	APPROX 35M OF DITCHING. PLEASE DISPOSE OF SPOIL OFF SITE.	Barlavington Lane	SUTTON	OPPOSITE SUTTON COURT BARN N497713 E115022 AND N497756 E115050
917055	please investigate/rod and repair gully id1236(Enquiry 10732)	Goose Green Lane	THAKEHAM	TM REQUIRED o/s works near to junction peacocks lane (see map on sharepoint) eastings:511374 northings:118807
918404	1linear metre of new 300mm pipe. concrete surround and reinstate verge	Willetts Lane	TILLINGTON	Outside drive of Timbers.
918884	Clear ditch as necessary and jet system as necessary(jetting completed 07/11/2012,see conways sheet in links (day crew digging out ditch to expose culvert)	A272 Brookfield Lane To Grittenham	TILLINGTON	junction of River Lane
918587	Please rod 2 x gullies Gully id D6529 and Gully id D6531 to clear blockages	Chithurst Lane	TROTTON-WITH-CHITHURST	north of Lassington and on the A272 from Corner cottage down to Trotton Bridge Between E:484260 N:122911 and E:484179 N:122837
918981	Drainage as per site specific sheet	Selsfield Road	TURNERS HILL	Roundabout to opposite Kingfisher Cottage 534134,135365 to 534114,135192
825413	rod from gully no. 3 as marked on the return, attempt to clear, dig down on break/block as found and repair and reinstate as existing and clear /regrade ditch as required (verge works) (Enquiry 243049)	Henfield Road	UPPER BEEDING	Approx 175mtrs north East of Rowwell, N/bound, See Map
193673	DIG DOWN AND REPAIR 150MM PIPE IN FOUR LOCATIONS 450MM TO INVERT. MARKED ON SITE. (NEAR TO SCHOOL)(this is a follow on job for job no 193452)	The Street	WALBERTON	2 SITES O/S BOOKERS YARD AND 2 SITES O/S AND OPPOSITE 1 PARK VIEW . BETWEEN 497097 106066 AND 497150 106051
915252	Hand dig and rod clear, (x2) gullies and gully chutes blocked by silt back to adjacent manholes. NOTE..site constrainr, work zone near to junction. (WS Obstd flood,spill,tree,hedge)	Barnham Lane	WALBERTON	Outside and opposite, No 1 Oaktree Cottages.
918323	DITCHING REQUIRED - the path that runs between Bell Road and the A24 clear ditch 32m long	Bell Road	WARNHAM	bell road between back of police house and bell road
64937	Rod and investigate possible broken pipe	East Street	WEST CHILTINGTON	outside hatches house as detailed on plan
917683	raise kerbs to 50mm upstand 8 number site has been visited before but not enough upstand	Roundabout Lane	WEST CHILTINGTON	outside property called Dalesbrook
916962	(Enquiry 10708) please rod 2 x gullies to outfall gully id D3792 and D3791	B2141 High St To East Marden Hill	WEST DEAN	east of Fish Restaurant between eastings:482635 northings:114493 and eastings:482692 northings:114469
916863	Drainage Investigate gullies as per site specific sheet as per conway report no 186	Horsted Lane	WEST HOATHLY	Between top road and clova 537634,132320 to 537752,131973
917018	remove jammed lid and hand empty gully	The Hollow	WEST HOATHLY	25m east glen rose cottage, eastings:536614 northings:132750
917976	Excavate in c/way onto broken pipe and repair as required Marked on c/way and f/w	Top Road	WEST HOATHLY	o/s The Lydd 537122,132463
918590	Drainage investigate,locate and clear blockages as per conway report 16642	Selsfield Road	WEST HOATHLY	Old selsfield to 56 534745,134328 to 534577,134582
918591	Drainage investigate, locate and clear blockage as per conway report 16640	Ardingly Road	WEST HOATHLY	Rock Cottage 534523,132441
63989	pump floodwater from eastern side of road to western outfall	Itchenor Road	WEST ITCHENOR	from outside Little court to outfall ditch adjacent to Gulworthy
917140	please cut vegetation/hedgerow to gain access and rod bewtween catchpit and gully (Enquiry 249723)	North Street	WESTBOURNE	opp Elm cottage (see conway sheet in sharepoint) EASTINGS:475642 NORTHINGS:107979
193788	TAKE OUT 4 SETTS AND CREATE AN 1MX1M APRON AND EXCAVATE A DITCH DOWN THE BACK OF THE BRIDGE SO WATER GOES INTO STREAM	Newpound Lane	WISBOROUGH GREEN	AT THE DRIVEWAY TO MOONSBROOK COTTAGE BETWEEN E505623 N126599 AND E505629 N126613
917136	Please Rod and repair as necessary	Water Lane	WISTON	Water Lane, Wiston and chanctonbury ring road between eastings:514391 northings:113522 and northings:113483
917117	Rod and if necessary replace pipe from verge to ditch Enquiry 409313)	A272 Severals Road To Woolbeding Lane	WOOLBEDING	" the A272 path between the cottage east of The Gallery and the Woolbeding turning EASTINGS:487257 NORTHINGS 121774: "
917589	scrape off mud/silt from carriageway(Call Back Requested) (Enquiry 260435)	Woolbeding Lane	WOOLBEDING	TM REQUIRED PRIORITY SIGNAGE PAI at the junction of Woolbeding lane, Hollist Lane & Bramblings Lane in Woolbeding.
918075	Suspected broken pipe, please investigate and repair as necessary	Linch Road	WOOLBEDING	Approx 250m south of old Post Office. See map links. between eastings:486249 northings:126035 and 486454 northings:125672
918415	excavate ditch (follow on job from job no 823113)	A272 Severals Road To Woolbeding Lane	WOOLBEDING	opposite Heathbarn Farm on Northern side of A272.between E:487382 N:121799 and E487101 N:121806
824394	Install new road gully, adjacent to B.T cover, lay 150mm x 8m to c'way inspection chamber. reinstate as existing, (dbm road surface)	Akehurst Close	WORTH	out 23, in c'way, adjacent to B.T cover in flw, (constraints junctions, overhead cables)
915582	investigate void and fix as necessary - no need for stats as void just under block paving	Montague Street	WORTHING	O/s Home Express opposite Waterstones, 10m west of Bath Place.
916577	rod gully to clear flood	Hythe Road	WORTHING	outside number 8
916662	Blocked drain outside cissbury court, rod gully to find block	Findon Road 120 To 124	WORTHING	Outside Cissbury court flats.
916834	PLEASE REPLACE GULLY	West Avenue	WORTHING	o/s 21 veh acc kerbside EASTINGS:513031 NORTHINGS:102932 (GULLY ID E1215)

916840	new gully required	Littlehampton Road Service Road	WORTHING	outside no 25
917264	key cut approx 100mm in front of side entry gullies (6 in total) to assist surface water to flow	Littlehampton Road Eastbound	WORTHING	Eastbound carriageway lane 2, approx 150m east of Yeoman Road Roundabout
917568	Flooding in George V Avenue. An officer has inspected one of the drains and told a resident that the drain had collapsed, however this drain has not been repaired as yet. Could somebody please inspect the drains to see if they need attention. (Enquiry 2	George V Avenue	WORTHING	Outside Burlington Court
917941	repair broken pipe under wall.site has been rodded and break is under wall	Wordsworth Road	WORTHING	on marine parade on junction with heene terrace by bus stop
917944	repair broken pipe	Salvington Hill	WORTHING	junction with Broadview Gardens
918634	rod gully to find any break in pipe	Littlehampton Road	WORTHING	North side of road o/s Carnegie House opposite 47. parked cars
918692	uncover buried gully & empty	Church Road to South Street	WORTHING	outside number 89 marked on site. be aware of parked vehicles